



## Flat leaf probes

**Type K Model 503K-TC1-ANP**  
**Type E Model 503E-TC1-ANP**




Temp. range	Tolerance	Response time	Durability
-50~210°C	±2.5°C (at 100°C)	3.0 s	S

**Type K Model 505K-TS1-ANP**  
**Type E Model 505E-TS1-ANP**




Temp. range	Tolerance	Response time	Durability
-50~400°C	±2.5°C (at 100°C)	6.0 s	S

**Type K Model 540K-TS1-ANP**  
**Type E Model 540E-TS1-ANP**



Temp. range	Tolerance	Response time	Durability
-50~100°C	±2.5°C (at 100°C)	8.0 s	S

### Flat leaf probes applications



## Insertion probes

**Type K Model 502K-TC1-ANP**  
**Type E Model 502E-TC1-ANP**




Temp. range	Tolerance	Response time	Durability
-50~210°C	±2.5°C (at 100°C)	3.0 s	S

**Type K Model 504K-TC1-ANP**  
**Type E Model 504E-TC1-ANP**




Temp. range	Tolerance	Response time	Durability
-50~500°C	±2.5°C (at 100°C)	6.0 s	S

### Insertion probes applications



## Sheet probes

**Type K Model 501K-TC1-ANP**  
**Type E Model 501E-TC1-ANP**



Temp. range	Tolerance	Response time	Durability
-50~250°C	±2.5°C (at 100°C)	4.0 s	S